

- A. If you are having issues with calibration for left and right, please refer to steps one(1) and two(2) below.
- B. By removing the nylon tie, this will put less stress on the wire harness that goes to the I/O board on top of the gun.

- 1. Remove the gun, and turn upside down
- 2. Remove the NYLON TIE

